


FIG. 1



2/11

FIG. 2








FIG. 4



5/11

FIG. 5




6/11

FIG. 6


	Rinsing		Drying1	Drying2	Drying3
HF Dip					
DIW					
DIW water-saving					
Slow up Speed					
Purge N <sub>2</sub>					
Quick Drain					
Porous plate <sub>IN</sub>					
IPA supply				N <sub>2</sub> IPA	
Dry N <sub>2</sub>					

(a)



8/11


FIG. 8






9/11

FIG. 9



10/11

FIG. 10



11/11

FIG. 11

